

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-006930**Date Inspected:** 19-May-2009**Project Name:** SAS Superstructure**OSM Arrival Time:** 645**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1845**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Zhao Chen Sun**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG components**Summary of Items Observed:**

On this date CALTRANS OSM Quality Assurance (QA) Inspector, Dilip Chakrabarti was present during the times noted above for observations relative to the work being performed.

Bay# 6-OBG Assembly

This QA Inspector randomly observed the following work in progress:

Magnetic Particle Testing (MT):

For Green Tag:

This QA inspector performed Magnetic Particle Testing (MT) of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a TL-6028 MT report on this date.

The member and the weld designations are as follows:

Sl # Section # Weld # Green Tag # Location

1. DP 205-012 002,004 007771 9 D
2. SP 206-015 002,004,006 007768 11 B
3. DP 204-012 001,003 007770 9 D
4. FB 201-014 11,13,15,17,19,21 007769 10 C

Bay# 6-Tower Assembly

This QA Inspector randomly observed the following work in progress:

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

SMAW Process:

Welding of weld joints# B/B-17 located on PCMK SSD1 DPSA4-2. Welder is identified as 037779. ZPMC QC is identified as Liu Hua Jie. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3312-TC-P5.

Welding of weld joints# B/B-16 located on PCMK SSD1 DPSA4-2. Welder is identified as 066481. ZPMC QC is identified as Liu Hua Jie. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3312-TC-P5.

Welding of weld joints# B/B-13 located on PCMK SSD1 DPSA4-2. Welder is identified as 066459. ZPMC QC is identified as Liu Hua Jie. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3312-TC-P5.

Welding of weld joints# B/B-12 located on PCMK SSD1 DPSA4-2. Welder is identified as 069493. ZPMC QC is identified as Liu Hua Jie. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-3312-TC-P5.

Bay # 7-OBG Assembly:

This QA Inspector randomly observed the following work in progress:

FCAW Process:

Welding of weld joints# 3&4 located on PCMK SP 204-015. Welder is identified as 054459. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132-3.

Welding of weld joints# 7&8 located on PCMK SP 204-015. Welder is identified as 051246. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132-3.

Welding of weld joints# 11&12 located on PCMK SP 204-015. Welder is identified as 062447. ZPMC QC is identified as Zhong Chong Biao. The welding variables recorded by QC appeared to comply with the specified WPS no. B-T-2132-3.

Unless otherwise noted, all work observed on this date appeared to be generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Inspected By:	Chakrabarti,Dilip Kumar	Quality Assurance Inspector
Reviewed By:	Clifford,William	QA Reviewer
